RS485 - USB Converter
Technical data-sheet

Specifications

Name:	RS485 - USB Converter
Dimensions:	8,6 x 5,7 x 2,7 cm (LxWxH)
Weight:	78 g
Accesories included:	miniUSB-USB cable

Electrical specifications

Power supply:	Powered by USB
Baud Rate:	4800 - 38400
Temp. Range:	From -20 to +70°C

Functions & features

Allows USB communication for devices based on RS485 line.

Applications

RS485 communication based device connection to USB.
AgrimagP2, MAGS1 sensor connection directly to PC.

Pictures

How to use the converter

Loop View

For detailed information about connection please see RS485-USB Converter manual.